

Report ID: 17,819,061 Version: 1 05 Sep 2019 Created:

Make:	Ford	Model:	Mondeo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2013	<b>Registration:</b>	MGW697	<b>Reg Expiry:</b>	25 Nov 2019	Engine			
WoF Expiry:	26 Oct 2019	Odometer:	132,058 Kms	Good No:	17819061	Oil level	~		
VIN:	WF0EXXGBBEDA5206	Next Service:	142100	Service Histor	<b>y:</b> No	Smoke & fumes	V		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and ti	his can be arranged fo	or an additional o	narge.	Coolant condition	~		
	S SC		S P SC S P SC		S SC	Performance	V		
Key:	1350	-0	3730 3730	500-	330	Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust PT = paint defect						Transmission			
						Operation	~		
						Noise	V		
C = crack					SC	Clutch			~
P = pin dent						CV joints	V		
* = decais						Wheel bearings	V		
SC = stone chips W = significant scuffs						Brakes			
W = significant scutts S SC S SC S SC SC SC SC						Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Minor stone chips in the windscreen ,						Tyres (lowest observed tread	d depth	of tyre	es)
						Left front 7 n			mm
						Right front		7	mm
						Left rear		7	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		mm
						Spare			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	V		
						Shock absorbers	V		
						Air Conditioning / Heater	1		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	wear and t	tear,minor stains	1			Head lights	~		
	Average					Tail lights	V		
Carpets	, it cluge					Indicators	V		
Panels	Average					Dashboard warning lights	V		
<u> </u>	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	·				-	Window winder FR	~		
General Comments						Window winder RL	V		
						Window winder RR	V		
						Rear view mirrors	V		
						Radio (basic test only)	V		
						CD (basic test only)	V		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Unknown						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
							1		1
Inspected by: Donovan Matara Date: 05 Sep 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....