

Report ID: 17,819,116 Version: 1 21 Aug 2019 Created:

| Make: | Holden | Model: | Commodore | Body Style: | Sedan | | Pass | Fail | N/A |
|--|--------------------------|----------------------|------------------------|-------------------|-----------------------|--|----------|------|-----|
| Year: | 2003 | Registration: | BQT928 | Reg Expiry: | 25 Jan 2020 | Engine | 1 | I | 1 |
| WoF Expiry: | 16 May 2020 | Odometer: | 223,697 Kms | Good No: | 17819116 | Oil level | ~ | | |
| VIN: | 6G1YK52AX4L156854 | Next Service: | 0 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | avation is maada | for one and miles as | Danta hava nat | heer discontinuity | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | Cooling System | | | |
| | ical inspection prior to | | | | | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | S SC S | -0 | SD SD | | S D PT SC | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | SDCSC | | | 1n- | ED SDC | Operation | ~ | | |
| R = rust | | | | 10 | | Noise | ~ | | |
| PT = paint def C = crack | ect | | | + | | Clutch | V | | |
| C = Crack P = pin dent | Ho | | | - | | | | | ~ |
| * = decals | SDCSC DC | | | | ELA S | CV joints | | ~ | |
| SC = stone chips | | | | | | Wheel bearings | ~ | | |
| W = significant scuffs | | | | | | Brakes | 1 | | 1 |
| | S D SC S | | SD SD | | S SC | Performance | ~ | | |
| Body Ins | pection Comments | Note: son | ne defects & blemishes | s may not be disp | blayed in the diagram | Hand Brake | ~ | | |
| Indicator missing from LF guard,moulding coming off LF door ,boot lid doesn't open, | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front 2 | | | mm |
| | | | | | | Right front | | 1 | mm |
| | | | | | | Left rear | | 3 | mm |
| Conditions During Body Inspection: Wet | | | | | | Right rear | 2 mm | | |
| | | | | | | Spare | N/A | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| Oil leaks fro | om top to bottom of mo | tor , | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | 1 | | 1 |
| | | | | | | Operation | | V | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | drivers sea | it ripped,wear ar | nd tear,stains , | | | Head lights | ~ | | |
| | | | | | | Tail lights | ~ | | |
| Carpets | wear and t | ear, stains , | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| Pariels | | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd Average | | | | | Window winder FL | | | |
| | | | | | | Window winder FL Window winder FR | v | | |
| General Comments | | | | | | Window winder FR Window winder RL | V | | |
| When driving car pulls hard to the right could wheel alignment but tyre is not road worthy and CVs and | | | | | | | ~ | | |
| | k needs attention , | - | 5 , 5 | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | | |
| Road Con | ditions During Test | t Drive: | Wet | | | Central locking | ~ | | |
| | anim m Maraharati | T ' ' | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| | dha Daran Mili | - | | | | | 10 | | |
| Inspected by: Donovan Matara Date: 21 Aug 2019 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: