

Basic Vehicle Condition Guide

Report ID: 17,819,279


Version: 1

Created: 05 Sep 2019

Make: Model: **Body Style:** Holden Captiva 7 SUV Year: 2013 Registration: GUG450 Reg Expiry: 14 Oct 2019 **Odometer:** WoF Expiry: **Good No:** 09 Apr 2020 194,724 Kms 17819279 VIN: KL3CD266JCB119380 Next Service: 207000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Minor stone chips in the windscreen,

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	drivers seat ripped, wear and tear ,		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Donovan Matara Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	V		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	4	1	mm
Right front	4	4	mm
Left rear	-	7	mm
Right rear	7		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	\(\triangle \)		
Air Conditioning / Heater			<u> </u>
Operation	~		
Electrical / Accessories			
Head lights	'		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V V V V V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	3		<u> </u>
Central locking	·		
Remote locking			
Sat. Nav. (basic test only)	V		
Reversing camera	~		-
carriera			

05 Sep 2019

Signature: