

Report ID: 17,819,734 Version: 2 02 Sep 2019 Created:

Make:	Holden	Model:	Captiva 7	Body Style:	SUV		Pass	Fail	N/A
Year:	2008	Registration:	·	Reg Expiry:	15 Oct 2019	Engine			
WoF Expiry:		Odometer:	246,990 Kms	Good No:	17819734	Oil level	~		
VIN:	KL3CD26GJ8B162307	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		f	Danta have a st	harriellen en alard an	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechar	ical inspection prior to	purchase and t	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	S SC	-0	S P SC S P SC	-M-	S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			L
D = dent	s sc			The	EII S	Operation	~		
R = rust PT = paint def				\int	JHIH	Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent					세비	CV joints	~		
* = decals	SPSC 916			The	ELL'S	Wheel bearings	~		
SC = stone chips						Brakes	•		<u> </u>
W = significant scuffs S S S S S S S S S S S S S S S S S S						Performance	~		
		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body inspection Comments						Tyres (lowest observed tread		of tyre	<u> </u>
Moisture inside the RR tail light and the LR tail light cracked ,									mm
						Right front	7		mm
						Left rear	7		mm
Conditions During Body Inspection: Wat						Right rear	7		 mm
Conditions During Body Inspection: Wet						Spare	,		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor oil le	ak,					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation		~	
Interior Comments						Electrical / Accessories		•	<u> </u>
Seats	drivers sea	at ripped,wear ar	nd tear ,			Head lights	~		
	A					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	A					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
					J	Window winder FR	~		
General Comments					Window winder RL	~			
Check engine light is on, traction control lights on,						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		L
Boad Con	ditions During Tes	t Drive	Wet			Central locking	· •		
						Remote locking	~		
Engine Timing Mechanism: Unknown						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
L	-								
Inspected by: Donovan Matara						Date: 02 Sep 2019			
I have read	and understood th	is condition g	juide. Name: .			Signature:			