

Basic Vehicle Condition Guide

Report ID: 17,819,752


Version: 2

Created: 11 Nov 2019

Make: Model: Hyundai lload **Body Style:** Van Year: 2016 Registration: JYQ954 Reg Expiry: 14 Jul 2020 Good No: WoF Expiry: **Odometer:** 15 Jul 2020 38,043 Kms 17819752 VIN: KMFWBX7KMGU8373: Next Service: 41000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Badges missing from tailgate, stone chips in the windscreen,

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	cigarette holes drivers seat,minor stains ,		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Donovan Matara

	Pass	Fail	N/A
Engine			•
Oil level	~		
Smoke & fumes	v v		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	1		
Clutch			~
CV joints	~		Ť
Wheel bearings	<i>'</i>		
Brakes			
Performance	V		
Hand Brake	<i>y</i>		
Tyres (lowest observed tread	denth	of tyre	L
Left front	· ·		mm
Right front	7		mm
Left rear	7		mm
Right rear		/ 7	mm
Spare	<u> </u>	/ Yes	111111
Suspension		168	
Suspension performance			
Steering performance	•		
Shock absorbers	•		
Air Conditioning / Heater	٠		
Operation			
Electrical / Accessories	_		
Head lights	•		
Tail lights			
Indicators			
	'		
Dashboard warning lights	· •/		
Wipers (front & rear)			
Wipers (front & rear) Window winder FL	\(\times \) \(\t		
Wipers (front & rear) Window winder FL Window winder FR	<i>v</i>		
Wipers (front & rear) Window winder FL Window winder FR Window winder RL			~
Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR			\ \ \
Wipers (front & rear) Window winder FL Window winder FR Window winder RL	<i>V</i>		\(\times \)
Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR	<i>'</i>		\(\times \)
Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors	<i>V</i>		\(\sigma \)
Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only)	VVVZ		\(\sigma \)
Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)	V V V V		V V
Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	V V V 2 V		\(\sigma \)
Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	V V V V		\(\sigma \)

I have read and understood this condition guide.

Name:

Signature: