

Note: This report is not a warranty

I have read and

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

			Coolant condition	~		
	SDP W SP	W SC	Performance	~		Γ
Key: l S = scratch			Radiator / Hoses (visual)	~		
D = dent			Transmission			
R = rust			Operation	~		[
PT = paint defect			Noise	~		
C = crack			Clutch			
P = pin dent	HR		CV joints	~		
^ = decais			Wheel bearings	2		
SC = stone chips W = significant scuffs			Brakes			
	W SSC	SC SC	Performance	~		
Body Inspection	Comments Note: some defects & b	blemishes may not be displayed in the diagram	Hand Brake	~		Γ
	in RF guard. Paint touchups on bonnet. Pin	n dent on LH sill. Clearcoat coming off high	Tyres (lowest observed tread	d depth	of tyre	s)
stop light.			Left front	2 m		
AC not cold. Heater controls worn. Stereo controls worn. Pocket lid in rear console not shutting. LCD screen in dash not working corectly.			Right front	2	2	m
			Left rear	4	1	m
Conditions During Body Inspection: Wet			Right rear	4	1	m
			Spare		Yes	
Under Carriage	Under Bonnet Inspection Comme	<u>ents</u>	Suspension			
Automatic transmis	ion has oil seepage and a dent in the sump.	·.	Suspension performance	~		
			Steering performance	~		
			Shock absorbers	~		[
			Air Conditioning / Heater			
			Operation		~	[
Interior Comme	nts		Electrical / Accessories			
Seats	Average		Head lights	~		
	Average		Tail lights	~		
Carpets			Indicators	~		ſ
Panels	Average		Dashboard warning lights	~		
Dashbaard Average		Wipers (front & rear)	~		Ī	
Dashboard			Window winder FL	~		l
			Window winder FR	~		ł
General Comments			Window winder RL			
Service lamp on.			Window winder RR			
Drives ok.			Rear view mirrors	~		ĺ
				-		<u> </u>

Report ID: 17,820,032 Version: 4 17 Dec 2019 Created:

Pass

V

V

V

V

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Fail

N/A

V

mm

mm

mm

mm

V

Service lamp on.	Window winder RR		~
Drives ok.	Rear view mirrors	~	
	Radio (basic test only)	~	
	CD (basic test only)	~	
	Number of keys	1	•
Road Conditions During Test Drive: Dry	Central locking	~	
· · · · · · · · · · · · · · · · · · ·	Remote locking	~	
Engine Timing Mechanism: Cambelt	Sat. Nav. (basic test only)		~
Evidence of Cam Belt Replacement: Yes Kms: 77,681	Reversing camera		~
Inspected by: Roger King	Date: 17 Dec 20	19	
nave read and understood this condition guide. Name:	Signature:		