

Basic Vehicle Condition Guide

Report ID: 17,820,078

Pass

1

V

/

V

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Suspension performance Steering performance

Spare

Right front

Coolant condition Performance

Radiator / Hoses (visual)

06 Sep 2019 Created:

Fail

N/A

1

mm

mm

mm

 mm

1

3

3

1

/

/

/

1

/


1

Yes

Make: Hyundai Model: Getz **Body Style:** Hatchback Year: 2005 Registration: CPQ42 **Reg Expiry:** 30 Sep 2019 WoF Expiry: **Odometer:** 21 Jan 2020 93,677 Kms **Good No:** 17820078 VIN: KMHBT31HR4U07884 **Next Service:** Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Headlights need attention, scratch marks in the right tail light, cracks in the right wing mirror, rust on the

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Minor oil leaks

wipers,

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Average			
Dashboard	Average			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Date:	06 Sep 2019

Evidence of Cam Belt Replacement: No	Kms:	Sat. Nav. (basic test only) Reversing camera	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Inspected by: Donovan Matara		Date: 06 Sep 2019	
I have read and understood this condition guide.	Name:	Signature:	