

 Report ID:
 17,837,444

 Version:
 1

 Created:
 15 May 2019

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2014	Registration:	HJD941	Reg Expiry:	25 Jun 2019	Engine	•		
WoF Expiry:	15 May 2020	Odometer:	114,811 Kms	Good No:	17837444	Oil level	~		
VIN:	VSKCVAD40A0530354	Next Service:	112201	Service Histor	' y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional	charge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	sw dla			715	HILD	Operation	~		T
PT = paint defe	ect NP	F I		$\left(\left \right \right)$		Noise	~		
C = crack				\square		Clutch			~
P = pin dent	HID				7444	CV joints			~
* = decals	- Alt			- John		Wheel bearings	~		-
SC = stone chips						Brakes			
W = significant scuffs W						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		1
Front bumper light cover missing						Tyres (lowest observed treat	d depth	of tyre	es)
						Left front			
						Right front	3	.0	mm
						Left rear	2	.5	mm
Conditions During Body Inspection: Dry						Right rear	2.5		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Right rear axle seal starting to weep						Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
		Shock absorbers	~		<u> </u>				
						Air Conditioning / Heater	1		1
						 Operation	~		Τ
Interior Comments						Electrical / Accessories			
Seats	drivers sea	at worn				Head lights	~		1
	Average					Tail lights	~		1
Carpets						Indicators	~		1
Panels	Average					Dashboard warning lights	~		1
	Average					Wipers (front & rear)	~		1
Dashboa	rd					Window winder FL	~		1
						Window winder FR	~		1
General Comments						Window winder RL	~		1
						Window winder RR	~		1
						Rear view mirrors	~		1
						Radio (basic test only)	~		1
						CD (basic test only)	~		1
						Number of keys	2	I	4
Road Conditions During Test Drive: Dry						Central locking	~		
		Remote locking	~		1				
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test onl									~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
Inspected	Inspected by: Greg Morgan Date: 13 May 2019								

I have read and understood this condition guide.

Name:

Signature: