

Basic Vehicle Condition Guide

Report ID: 17,839,456

Pass

1

V

/

V

1

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of kevs

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Right front

Coolant condition Performance

Radiator / Hoses (visual)

05 Sep 2019 Created:

Fail

N/A

1

mm

mm

mm

 mm

5.0

5.0

6.0

7.0

1

/

/

1

V


2

Yes

Make: Holden Model: Cruze **Body Style:** Wagon Year: 2016 Registration: JZY868 **Reg Expiry:** 01 Nov 2019 **WoF Expiry: Odometer:** 19 Aug 2020 89,792 Kms **Good No:** 17839456 VIN: KL3JA35MJGK339794 **Next Service:** 108000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Greg Morgan

I have read and understood this condition guide.

Evidence of Cam Belt Replacement: No

		_	_	
	Central locking	V		
	Remote locking	~		
	Sat. Nav. (basic test only)		~	
Kms:	Reversing camera		~	
	Date: 05 Sep 20	19		
Name:	Signature:			