

Basic Vehicle Condition Guide

Report ID: 17,845,394


Version: 1

Created: 23 Oct 2018

Make: Model: Holden Commodore **Body Style:** Sedan Year: 2015 Registration: Reg Expiry: **JAA275** 15 Mar 2019 WoF Expiry: **Odometer:** 21 Oct 2019 **Good No:** 17845394 60,457 Kms VIN: **Next Service: Service History:** 6G1FB5E37FL105769 n/a Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



body inspection comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	<u>S</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: lan Dunn Date: 23 Oct 2018

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	\(\triangle \)		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	>		
Wheel bearings	~		
Brakes			
Performance	V		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	7	.3	mm
Right front	6.6		mm
Left rear	6.9		mm
Right rear	6	.5	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	V		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	>		
Wipers (front & rear)	\(\times \)		
Window winder FL	>		
Window winder FR	\(\times \) \(\t		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		

I have read and understood this condition guide.

Name:			