

Basic Vehicle Condition Guide

Report ID: 17,846,031


Version: 1

Created: 26 Nov 2018

Make: Model: Holden Captiva 5 **Body Style:** SUV Year: 2015 Registration: JMK801 Reg Expiry: 06 Mar 2019 WoF Expiry: **Odometer: Good No:** 23 Nov 2019 159,817 Kms 17846031 VIN: KL3DD2669FB053839 Next Service: 161,000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Small engine oil leak

Interior Comme	<u>ents</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: lan Dunn Date: 26 Nov 2018

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	<i>V V</i>		
Radiator / Hoses (visual)	~		
Transmission	•	•	•
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes	l		
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	l depth	of tyre	⊥ ≘s)
Left front	I	.8	mm
Right front	3.6		mm
Left rear	2.8		mm
Right rear	3.2		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	\(\sigma \)		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	~		
Tail lights			
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	\(\times \)		
Window winder FL	~		
Window winder FR	\(\times \)		
Window winder RL	<i>y</i>		
Window winder RR	· ·		
Rear view mirrors	~		
Radio (basic test only)	Ι.		
CD (basic test only)	\(\triangle \)		
Number of keys			
Central locking	2		
	1		
Remote locking			
Sat. Nav. (basic test only)			-
Reversing camera	V	l	1

I have read and understood this condition guide.

Name:

Signature: