

Basic Vehicle Condition Guide

Report ID: 17,848,512


Version: 1

Created: 08 Mar 2019

Make: Model: Nissan Primera **Body Style:** Wagon Year: 1997 Registration: **BAM138** Reg Expiry: 01 Oct 2018 WoF Expiry: **Odometer:** 28 Feb 2019 262,962 Kms **Good No:** 17848512 VIN: 7A8DH2G0702100256 **Next Service:** 265,287 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Front windscreen stone chips Front bumper detached from fenders

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine oil leak Rear wheels bent

| Interior Comments | | |
|-------------------|------|--|
| Seats | Good | |
| Carpets | Good | |
| Panels | Good | |
| Dashboard | Good | |

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

| | Pass | Fail | N/A |
|------------------------------|--|---------|---------|
| Engine | | | 1, |
| Oil level | V | | |
| Smoke & fumes | \(\times \) | | |
| Performance | 1/ | | |
| Noise | • | | |
| Cooling System | | | |
| Coolant condition | | | |
| Performance | | | |
| Radiator / Hoses (visual) | <i>v</i> | | |
| , , | <i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i> | | |
| Transmission | | | |
| Operation | <i>V</i> | | |
| Noise | - | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | ı | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 4 | .1 | mm |
| Right front | 4 | .7 | mm |
| Left rear 4.3 | | mm | |
| Right rear 4.8 | | .8 | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | <i>V</i> | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | | | ~ |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | | | |
| Wipers (front & rear) | v | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | | ~ | |
| Window winder RR | · | - | |
| Rear view mirrors | · | | |
| | Ļ. | | |

I have read and understood this condition guide.

lan Dunn

| Namo. | |
|-------|--|
| | |

Signature:

06 Mar 2019

1

1

Radio (basic test only)
CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Date: