

Report ID: 17,849,732


Version: 1

Created: 30 Apr 2019

Make:	Holden	Model:	Colorado	Body Style:	Utility
Year:	2013	Registration:	HFE90	Reg Expiry:	29 Jun 2019
WoF Expiry:	28 Dec 2019	Odometer:	189,801 Kms	Good No:	17849732
VIN:	MMU148EK0EH61252	Next Service:	198,000	Service Histor	y: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Badges missing, left taillight chipped, side canopy locks missing

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments						
Seats	Good					
Carpets	Good					
Panels	Good					
Dashboard	compartment lid on dash broken					

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:**

No

Kms:

Name:

Inspected by: Kyle Kelly Date: 30 Apr 2019

	Pass	Fail	N/A
Engine	•	•	
Oil level	~		
Smoke & fumes	~		
Performance	V		
Noise	~		
Cooling System	•		
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•	!	
Operation	~		
Noise	~		
Clutch	\(\times \)		
CV joints	~		
Wheel bearings	~		
Brakes			1
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	6	.0	mm
Right front	6	.0	mm
Left rear	5	.5	mm
Right rear	6	.0	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	1		1
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)			
Window winder FL	v		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)	· ·		~
Reversing camera			1
		<u> </u>	<u> </u>
D . 20 A 20	10		

Signature: