

## **Basic Vehicle Condition Guide**

Report ID: 17,855,939

Pass

1

~

/

V

1

Tyres (lowest observed tread depth of tyres)

Version: 3

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

**Transmission** 

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Right front

Left rear

Right rear

Suspension

Suspension performance Steering performance

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Operation

Head lights Tail lights Indicators

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 16 Oct 2019

Fail

N/A

1

mm

mm

mm

 $\mathsf{mm}$ 

6.0

6.0

6.0

7.0

1

/

/

1

~

2

1


~ ~

Yes

Make: Model: Ford Territory **Body Style:** SUV Year: 2016 Registration: KBL610 **Reg Expiry:** 12 Dec 2019 WoF Expiry: **Odometer:** 30 Sep 2020 80,294 Kms **Good No:** 17855939 VIN: 6FPAAAJGATGC22089 Next Service: 90695 km **Service History:** Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

**General Comments** 

**Road Conditions During Test Drive:** Dry

	Remote locking	V	l		
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No	Kms:	Sat. Nav. (basic test only) Reversing camera			
Inspected by: Eddie Marsters	spected by: Eddie Marsters		Date: 19 Sep 2019		
nave read and understood this condition guide.	Name:	Signature:			