

Report ID: 17,860,219 Version: 1 26 Apr 2018 Created:

Make:	Mazda	Model:	Mazda2	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,010	Registration:	FLG555	Reg Expiry:	27 Jul 2018	Engine	1		
WoF Expiry:	22 Jul 2018	Odometer:	20,875 Kms	Good No:	17860219	Oil level	~		
VIN:	MM0DE10Y10012479	Next Service:	28000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission	I I		
D = dent R = rust	s di			715	HILS	Operation	~		
PT = paint defe				$\left[\right] \left[\right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74114	CV joints	~		-
* = decals				The	ALL S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs	$- \varnothing$	S			Performance	~		
		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Insp	pection Comments			, ,	, ,	Tyres (lowest observed tread	-	of tyre	s)
									mm
						Right front	3.		mm
						Left rear			mm
						Right rear	5.0		mm
Conditions During Body Inspection: Dry						Spare	5.0		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
Air Conditioning / Heat							•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys			
						Central locking	2		
Road Conditions During Test Drive: Dry Central locking Remote locking Remote locking							~		
Engine Ti	ning Mechanism:	Timing (Chain			Sat. Nav. (basic test only)	~		
Evidence of Cam Bolt Deplacement:									v
						Reversing camera			~
Inspected by: Jeff Luke Date: 23 Apr 2018									

I have read and understood this condition guide.

Name:

Signature: