

I have read and understood this condition guide.

Report ID: 17,861,826 Version: 4 Created: 29 Sep 2018

Signature: .....

Make:	Mitsubishi	Model:	Outlander	Body Style:	SUV		Pass	Fail	N/A
Year:	2005	<b>Registration:</b>	GRC73	Reg Expiry:	06 Mar 2019	Engine	1	I	
WoF Expiry:	24 Sep 2019	Odometer:	183,154 Kms	Good No:	17861826	Oil level	~		
VIN:	7AT0CJ3MX12004422	Next Service:	186,077	Service Histor	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for and milago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	SD	-0	S S	-M-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation 🖌			
R = rust PT = paint defect						Noise	~		
C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		
* = decals	SP 916			- AL	ETP D	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S S S						Performance			
		Note: som	ne defects & blemishes	may not be disn		Hand Brake	~		
	pection Comments	10000.3011	le delects à blemistie	s may not be disp	ayed in the diagram			ofture	) )
Front bumper misaligned Front windshield mouldings insecure					Tyres (lowest observed tread depth of tyres)			-	
						Left front		4	mm
						Right front		5	mm
						Left rear		2	mm
Conditions During Body Inspection: Dry								mm	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	-	inet inspectic	<u>In comments</u>			Suspension			
Engine oil le	еак					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	roor					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)		~	
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking							~		
						Remote locking		~	
-	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Ca Thach Date: 29 Sep 2018									

Name: .....