

Report ID: 17,862,094 Version: 1 30 Apr 2018 Created:

Make:	Mitsubishi	Model:	Outlander	Body Style:	SUV		Pass	Fail	N/A
Year:	2,014	Registration:	HND171	Reg Expiry:	08 Jul 2018	Engine			
	2,014 07 Jul 2018	Odometer:	81,279 Kms	Good No:	17862094	Oil level	~		
VIN:	JMFXTGF8WEZ002826		,	Service Histor		Smoke & fumes	~		
			07000		, NO	Performance	~		
Note: This report is not a warranty						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
		_				Performance	~		
Key:	S SC	-0	S P SC S SC		S P SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation			
R = rust				10		Noise	ン ン		<u> </u>
PT = paint def C = crack	ect III			+	SC	Clutch	V		
P = pin dent	Ho								~
* = decals	s sc pp			SI_		CV joints	~		<u> </u> !
SC = stone chips						Wheel bearings	~		
W = significant scuffs S SC S SC						Brakes			
						Performance	~		<u> </u>
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~	6 .	
						Tyres (lowest observed tread			
						Left front	7 mm		
						Right front	7	7	mm
						Left rear	7		mm
Conditions During Body Inspection: Dry						Right rear	7 mm		
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average				Dashboard warning lights	~			
Dashboa	rd Average					Wipers (front & rear)	<		
						Window winder FL	~		
	-					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		·
Road Conditions During Test Drive: Dry						Central locking	~		
			-			Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera	~		
						L			
Inspected by: Donovan Matara Date: 30 Apr 2018									
I have read and understood this condition guide. Name:									