

Report ID: 17,863,612 Version: 1 28 Jun 2018 Created:

Make:	Hyundai	Model:	lmax	Body Style:	People Mover		Pass	Fail	N/A
Year:	2,016	Registration:	KAB506	Reg Expiry:	30 Apr 2018	Engine			L
WoF Expiry:	,	Odometer:	57,390 Kms	Good No:	17863612	Oil level	~		
VIN:	KMHWH81KMGU8376	Next Service:		Service Histor		Smoke & fumes	v		
					· ·	Performance	~		
	port is not a warranty	avation is made	for one and miles as	Danta hava nat	heen discontinuing or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		-0	P PSC			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sc			The		Operation	~		
R = rust				10	THIA	Noise	~		
PT = paint def C = crack				$\square \bigcirc$	SC	Clutch			~
P = pin dent	Ho				JUII —	CV joints			~
* = decals	sc pp			AL-	ELTR.				
SC = stone chips						Wheel bearings Brakes	~		
W = significant scuffs									<u> </u>
		Notor con			laved in the diagram		~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake			
Left taillight cracked.						Tyres (lowest observed tread depth of tyres)			
						Left front		5	mm
						Right front	6	-	mm
						Left rear		7	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	mage & onder bor	mermspectic	<u>on comments</u>			Suspension	1		
						Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
-	-					Window winder FR	~		
<u>General (</u>	<u>Comments</u>					Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera	~		<u> </u>
Inspected by: Brian Hill Date: 28 Jun 2018									
I have read and understood this condition guide. Name:									