

Report ID: 17,864,135 Version: 1 26 Apr 2018 Created:

Make:	Nissan	Model:	Tiida	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,008	Registration:	Indu	Reg Expiry:	Hutenbuck	Engine			
WoF Expiry:		Odometer:	41,179 Kms	Good No:	17864135	Oil level	~		
VIN:	7AT0DH78X18196326	Next Service:	51,000kms	Service History		Smoke & fumes	~		
	////02///0//190520		51,000 kms			Performance	~		<u> </u>
	port is not a warranty		<i>с</i> н.н.			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch	Se	20		105	*	Transmission	V		
D = dent	- Alle				EID ~	Operation			<u> </u>
R = rust				10			v		
PT = paint def	ect 1			$ \cup$		Noise	~		
C = crack P = pin dent	LH		لــــاز			Clutch			~
* = decals	dic					CV joints	~		
SC = stone chi	ps U			10		Wheel bearings	~		
W = significant scuffs						Brakes			
						Performance	~		<u> </u>
Body Insp	pection Comments	Note: som	e defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	4	ŀ	mm
						Right front	4	ŀ	mm
						Left rear	3	8	mm
Conditions During Body Inspection: Dry						Right rear	3 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Ok, dry .						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
<u></u>	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Card					Wipers (front & rear)	~		-
Dashboa	rd Good					Window winder FL	~		
	I					Window winder FR	~		
General Comments					Window winder RL	~			
Good looking,nice driving hatch .						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys			L
							1		<u> </u>
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
Engine Ti	ming Mechanism:	Timina	- hain			Remote locking	~		<u> </u>
						Sat. Nav. (basic test only)			~
			lot Applicable	11113.		Reversing camera	~		
Inspected by: Daryll Timms Date: 26 Apr 2018									

I have read and understood this condition guide.

Name:

Signature: