

Basic Vehicle Condition Guide

Report ID: 17,865,529


Version:

Created: 08 Jun 2018

Make: Model: Mazda Demio **Body Style:** Hatchback Year: 2,008 Registration: HDA706 Reg Expiry: 22 Jul 2018 WoF Expiry: **Odometer:** 23 May 2019 **Good No:** 17865529 156,911 Kms VIN: 7AT0C12HX13146824 **Next Service: Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Small stop chip on front windscreen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Under bonnet surface rust

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

23 May 2018 Inspected by: Rahul Singh Date:

| e.eute | | | | | |
|--|--|------|-----|--|--|
| | Pass | Fail | N/A | | |
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | ~ | | | | |
| Performance | VVV | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | ~ | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread depth of tyres) | | | | | |
| Left front | 5 | .0 | mm | | |
| Right front | 5 | .0 | mm | | |
| Left rear | 5.0 | | mm | | |
| Right rear | 5.0 | | mm | | |
| Spare | Yes | | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | ~ | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation 🗸 | | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | ~ | | | | |
| Dashboard warning lights | ~ | | | | |
| Wipers (front & rear) | \(\times \) \(\t | | | | |
| Window winder FL | ~ | | | | |
| Window winder FR | ~ | | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | V | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | ~ | | | | |
| Number of keys | 1 | | | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | | | ~ | | |
| | | | | | |

I have read and understood this condition guide.

Name:

Signature: