

Basic Vehicle Condition Guide

Report ID: 17,869,289


Version: 3

Created: 21 Nov 2018

Make: Model: Holden Captiva 7 **Body Style:** SUV Year: 2017 Registration: KHL481 Reg Expiry: 01 May 2018 WoF Expiry: **Odometer: Good No:** 11 Jan 2020 38,217 Kms 17869289 VIN: **Next Service:** KL3CD2659GB538171 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips on front windscreen

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A		
Engine					
Oil level	~				
Smoke & fumes	~				
Performance	\(\triangle \)				
Noise	~				
Cooling System					
Coolant condition	~				
Performance	~				
Radiator / Hoses (visual)	V				
Transmission					
Operation	~				
Noise	~				
Clutch			~		
CV joints	~				
Wheel bearings	~				
Brakes					
Performance	~				
Hand Brake	~				
Tyres (lowest observed treac	l depth	of tyre	es)		
Left front		3	mm		
Right front		3	mm		
Left rear		3	mm		
Right rear	:	3	mm		
Spare		Yes			
Suspension					
Suspension performance	~				
Steering performance	~				
Shock absorbers	~				
Air Conditioning / Heater					
Operation	~				
Electrical / Accessories					
Head lights	~				
Tail lights					
Indicators	V				
Dashboard warning lights	~				
Wipers (front & rear)	~				
Window winder FL	V				
Window winder FR	'				
Window winder RL	~				
Window winder RR	~				
Rear view mirrors	~				
Radio (basic test only)	~				
CD (basic test only)	~				
Number of keys	2		•		
Central locking	~				
Remote locking	~				
Sat. Nav. (basic test only)			~		
Reversing camera	~				
D : 241 222					

I have read and understood this condition guide.

Xinghui Lin

Name:

Signature:

Date: 21 Nov 2018