

Basic Vehicle Condition Guide

Report ID: 17,871,184


Version:

Created: 02 May 2018

Make: Model: Vista **Body Style:** Sedan Toyota Year: 1,999 Registration: CJF223 Reg Expiry: 14 Nov 2018 WoF Expiry: **Odometer: Good No:** 17871184 15 Jul 2018 257,813 Kms VIN: 7A8H6070704014125 **Next Service: Service History:** not known

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

No cargo blind. Door remote worn out.

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

CV boots split and joints are noisy.

Interior Comments		
Seats	Average	
Carpets	Average	
Panels	Poor	
Dashboard	Good	

General Comments

Runs well

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

Date: 02 May 2018 Inspected by: Brian Hill

Pass	Fail	N/A
\(\times \) \(\t		
\(\times \)		
V V		
V V		
V	1	
		~
	~	
~		
~		
~		
d depth	of tyre	es)
	5	mm
	5	
4		mm
	4	
	Yes	
~		
~		
~		
!		
~		
~		
~		
~		
V		
~		
~		
·		
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
V		
4		
1		
1		
1		V
1		<i>V</i>
		4 4 Yes

I have read and understood this condition guide.

Name:

Signature: