

Report ID: 17,872,473 Version: 1 Created: 05 May 2018

Make:	Mazda	Model:	Demio	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,007	<b>Registration:</b>	HEU399	Reg Expiry:	05 Aug 2018	Engine	1	I	
WoF Expiry:	20 Apr 2019	Odometer:	133,227 Kms	Good No:	17872473	Oil level	~		
VIN:	7AT0C12HX13102229	Next Service:	Unknown.	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	pration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	IS IS		S R	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s d			TIS	HILS	Operation	~		
R = rust PT = paint defe				$\prod$		Noise	~		
C = crack					S SC	Clutch			~
P = pin dent	HID				ᅰᇉ	CV joints	~		
* = decals	SPSC 916			- NG	ALC D	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W S S						Performance	~		
Podulaci		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	depth	of tyre	es)
					Left front 2 mm				
						Right front		2	mm
						Left rear		2	mm
Conditions During Body Inspection: Dry						Right rear	2 mm		mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance		~	
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories	I		
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	· ·					Window winder FR	~		
General Comments					Window winder RL	~			
Knocking n	oise from front					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking									
			-			Remote locking		~	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Mathew Varghese Date: 05 May 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....