

Report ID: 17,872,954 Version: 2 Created: 13 Aug 2018

Make:	Subaru	Model:	Outback	Body Style:	SUV		Pass	Fail	N/A
Year:	2,014	Registration:	HNP147	Reg Expiry:	20 Jul 2018	Engine			
WoF Expiry:	21 Jul 2018	Odometer:	143,059 Kms	Good No:	17872954	Oil level	~		
VIN:	JF2BRMKC5EG064314	Next Service:	154000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	avation is made	for one and miles as	Danta hava nat	heen discontined or	Noise	·		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:		-0	SP SP	-161-	PT	Radiator / Hoses (visual)	·		
S = scratch						Transmission			
D = dent	sc di			TIS		Operation	~		
R = rust PT = paint defe				$\left[\right] \left[\right]$		Noise	v		
C = crack					SC	Clutch	-		~
P = pin dent	HID				74 <u>11</u>	CV joints	~		
* = decals	sc 916			- Jul	ALC S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan			P PSC			Performance	v		
Body Incr	oction Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
						Left front	8		mm
						Right front	8		mm
						Left rear	8		mm
Conditions During Body Inspection: Wet						Right rear	8 mm		
vice						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
_						Window winder FR	~		
General Comments					Window winder RL	~			
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet Central locking							~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Bobby Zhong Date: 13 Aug 2018									

I have read and understood this condition guide.

Name:

Signature: