

Report ID: 52,079 Version: 1 Created: 29 May 2018

Make:	Mercedes-Benz	Model:	C180	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2,006	Registration:	JKD506	Reg Expiry:	13 May 2018	Engine				
WoF Expiry:	24 May 2019	Odometer:	78,182 Kms	Good No:	17873729	Oil level	~			
VIN:	WDC2030462R210795	Next Service:	86000	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	charge.	Coolant condition	~			
						Performance	~			
Key:		-0	ls	-161-		Radiator / Hoses (visual)	~			
S = scratch							Transmission			
						Operation	~			
R = rust PT = paint def				1 M	JHH	Noise	~			
C = crack				+		Clutch	-		~	
P = pin dent						CV joints	~			
* = decals	616			T	EITR	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S S S										
		Noto: con	ne defects & blemishes		laved in the diagram	Hand Brake	~ ~			
Body Inst	pection Comments	Note. son	le délects & blemisnes	s may not be disp	hayed in the diagram		•			
						Tyres (lowest observed tread depth of tyres)				
						Left front		.0	mm	
						Right front		.0	mm	
r						Left rear	-	7	mm	
Conditions During Body Inspection: Dry						Right rear	7.0 m		mm	
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes			
onder Carnage & onder Bonnet inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
		Shock absorbers	~							
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Carnota	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
	Good					Wipers (front & rear)	~			
Dashboa	ru					Window winder FL	~			
L						Window winder FR	~			
General Comments						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
Inspected by: Ben Date: 07 May 2018										

I have read and understood this condition guide.

Name:

Signature: