

Report ID: 17,874,090 Version: 1 14 May 2018 Created:

Make:	Holden	Model:	Captiva 7	Body Style:	SUV		Pass	Fail	N/A
Year:	2,017	Registration:	LDT466	Reg Expiry:	01 May 2018	Engine		-	
WoF Expiry:	2,017	Odometer:	41,747 Kms	Good No:	17874090	Oil level	~		
VIN:	KL3CD2659GB538418	Next Service:	45000	Service Histor		Smoke & fumes	~		
			15000		/ 110	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
		_				Performance	~		
Key:		-0	LIS		S	Radiator / Hoses (visual)	~		
S = scratch	STE	A CO			X	Transmission	V		
D = dent	Alt			1 - L	BID	Operation	~		<u> </u>
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack	ect III			+		Clutch	V		~
P = pin dent	Ho						~		~
* = decals	- MIC			AL-		CV joints	-		
SC = stone chi	ps US	VA		10		Wheel bearings Brakes	~		
W = significant scuffs W									<u> </u>
						Performance	~		<u> </u>
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake		<i>C</i> .	Ļ
Right and left front tyre flat					Tyres (lowest observed tread depth of tyres)				
						Left front	5		mm
						Right front	5	5	mm
						Left rear	4	1	mm
Conditions During Body Inspection: Wet						Right rear	4 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	mage & onder bor	mermspectic	<u>In comments</u>			Suspension			. <u> </u>
						Suspension performance	~		<u> </u>
						Steering performance	~		-
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Interior Comments Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dashboa	iu					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	2		
						Rear view mirrors	<		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Wet Central locking							~		
						Remote locking	~		
-	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: John Lindsay Date: 14 May 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....