

Report ID: 17,874,116 Version: 1 Created: 08 May 2018

| Make: | Hyundai | Model: | 145 | Body Style: | Sedan | | Pass | Fail | N/A |
|--|--------------------------|----------------------|------------------------|-------------------|----------------------|--|------|----------|-----|
| Year: | 2,012 | Registration: | GMK593 | Reg Expiry: | 27 Sep 2018 | Engine | 1 | <u> </u> | |
| WoF Expiry: | 02 Oct 2018 | Odometer: | 118,500 Kms | Good No: | 17874116 | Oil level | ~ | | |
| VIN: | KMHEC41DMCA46684 | Next Service: | 115000 | Service Histor | V: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | aration is made | for age and mileage | Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechar | ical inspection prior to | purchase and th | his can be arranged fo | r an additional o | harge. | Coolant condition | ~ | | |
| | SC | | SC SC | | SC | Performance | ~ | | |
| Key: | Bell | -0 | | 500- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | | Transmission | | | 1 |
| R = rust | s sc | | | 210 | | Operation | ~ | | |
| PT = paint def | ect NP | | | | | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | s sc dl | | | | 2416 | CV joints | ~ | | |
| * = decals | | 10 | | 10 | | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| W = significan | SC | | SC | | | Performance | ~ | | |
| Body Insi | pection Comments | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | 7 | 7 | mm |
| | | | | | | Right front | 7 | 7 | mm |
| | | | | | | Left rear | 7 | 7 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 7 mm | | |
| | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| Shock abso | | | | | | | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation 🖌 | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| Carpets | Average | | | | | Tail lights | ~ | | |
| | | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| Dashboa | rd Average | | | | | Wipers (front & rear) | ~ | | |
| Dastibua | | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| <u>General (</u> | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| F actor 7 1 | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Unknown | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| Incracta | d by: Donovan Matar | | | | | Date: 08 May 20 | 18 | | |
| Inspected by: Donovan Matara Date: 08 May 2018 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: