

## **Basic Vehicle Condition Guide**

Report ID: 17,874,233

Version:

Engine

Created: 18 May 2018

Fail

N/A

1


mm  $\mathsf{mm}$ mm

 $\mathsf{m}\mathsf{m}$ 

1

Pass

Make: Model: **Body Style:** Holden Barina Hatchback Year: 2,016 Registration: KDC585 **Reg Expiry:** 31 May 2018 **WoF Expiry: Odometer: Good No:** 35,607 Kms 17874233



Road Conditions During Test Drive: Wet

**Engine Timing Mechanism:** Cambelt

Jason Law

Inspected by:

**Evidence of Cam Belt Replacement:** No

I have read and understood this condition guide.

Remote locking Sat. Nav. (basic test only) 1 Kms: Reversing camera 18 May 2018 Name: .... Signature: .....

Central locking

WoF Expiry:	1	Odometer:	35,607 Kms	Good No: 1	7874233	Oil level	~		
VIN:	KL3TA48E9HB029278	Next Service:		Service History:	Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty  This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Noise	~		
						Cooling System			
a full mecha	anical inspection prior to	purchase and t	nis can be arranged	a for an additional cha	arge.	Coolant condition	<b>'</b>		
			D			Performance	~		_
Key:		$=$ $\langle \Omega \rangle$		$\pm (0) \pm$		Radiator / Hoses (visual)	~		_
S = scratch D = dent R = rust PT = paint defect C = crack P = pin dent * = decals						Transmission			
						Operation	V		_
						Noise	~		_
						Clutch			-
						CV joints	~		_
						Wheel bearings	~		_
SC = stone chips W = significant scuffs						Brakes			
vv = significa	P S		PP	S	P	Performance	V		_
Rody In	spection Comments	Note: son	ne defects & blemis	hes may not be display	yed in the diagram	Hand Brake	~		_
Body Inspection Comments  Water inside right tail light						Tyres (lowest observed tread depth of tyres			
water mis	ac right tall light					Left front	4	ļ	m
						Right front	4	 I	m
						Left rear	3	3	m
Conditions During Body Inspection: Wet						Right rear	4		m
wet						Spare		Yes	_
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	V		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater		ı	_
						Operation	V		
Interior	Comments					Electrical / Accessories			
Seats	Good					Head lights	V		
	floor mat r	missina				Tail lights	~		
Carpets	5					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashbo	pard					Window winder FL	~		
					Window winder FR	~			
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			-
						Number of keys	2		
									_