

Report ID: 17,875,655 Version: 1 Created: 04 May 2018

Make:VolkswagenModel:PoloBody Style:HatchbackPassFailYear:2,009Registration:Reg Expiry:Reg Expiry:EngineWoF Expiry:24 Apr 2019Odometer:69,567 KmsGood No:17875655Oil level✓-VIN:WVWZZZ9NZ9U0155Next Service:79,562kmsService History:NoSmoke & fumes✓-Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled orNoise✓-	N/A
WoF Expiry: 24 Apr 2019 Odometer: 69,567 Kms Good No: 17875655 VIN: WVWZZZ9NZ9U01558 Next Service: 79,562kms Service History: No Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or Performance ✓	
VIN: WVWZZZ9NZ9U0155{ Next Service: 79,562kms Service History: No Smoke & fumes ✓ Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or Performance ✓	
Note: This report is not a warranty Performance Image: Comparison of the second s	
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or	
I his report is a guide only. Consideration is made for age and mileage. Parts have not been dismantied or	
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends Cooling System	
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.	
Performance V	
Key: Radiator / Hoses (visual)	
S = scratch	
D = dent	
R = rust PT = paint defect Noise V	
Cercrack	V
P = pin dent CV joints V	•
* = decals QIQ Wheel bearings V	
SC = stone chips	
W = significant scuffs Performance V	
Note: come defecte 8 blemiches may not be displayed in the dispram	
body inspection comments	
Tyres (lowest observed tread depth of tyre Left front 6	
	mm
Right front 6	mm
Left rear 6	mm
Conditions During Body Inspection: Dry Right rear 6	mm
Under Carriage & Under Bonnet Inspection Comments Spare Yes Suspension	
Steering performance	
Shock absorbers	
Air Conditioning / Heater	1
Interior Comments	
Good	
Seats Head lights V	
Carpets Good Tail lights 🗸	
Good Indicators	
Panels Dashboard warning lights 🗸	
Good Wipers (front & rear) Windexweinder Flue Image: Constraint of the flue	
Window winder FL	
General Comments	
Nice driving little batch	
Window winder KK	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	
Number of keys 1	
Road Conditions During Test Drive: Dry Central locking ✓	
Engine Timing Mechanism: Cambelt Sat Nav. (basic test only)	
Suidence of Com Bolt Dank comparts and Kings	~
Evidence of Cam Belt Replacement: No Kms: Reversing camera	~
Inspected by: Daryll Timms Date: 04 May 2018	

I have read and understood this condition guide.

Name:

Signature: