

Basic Vehicle Condition Guide

Report ID: 17,875,705


Version: 1

Created: 04 May 2018

Make: Model: Mercedes-Benz B170 **Body Style:** Wagon Year: Registration: Reg Expiry: 2,009 **WoF Expiry: Odometer: Good No:** 26 Apr 2019 17875705 41,053 Kms VIN: WDD2452322J411563 **Next Service: Service History:** 51,100kms

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

<u>Under Carriage & Under Bonnet Inspection Comments</u>

OK, dry.

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

General Comments

Nice car, drives fine.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Daryll Timms Date: 04 May 2018

Name:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
	!	-
~		
~		
		~
~		
<i>y</i>		
·/		
•		
l denth	of tyre)
		mm
		-
		mm
		mm
		mm
	Yes	
		1
•		
•		
•		
		1
•		
	ı	
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
•		
~		
~		<u> </u>
1		
1		· ·
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ

Signature: