

Basic Vehicle Condition Guide

Report ID: 17,875,975


Version:

Created: 03 May 2018

Make: Model: Nissan **Body Style:** Sedan Teana Year: 2,008 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 27 Apr 2019 17875975 97,832 Kms VIN: 7AT0DH71X18505366 **Next Service:** 107,888kms **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Clean, tidy & dry.

Interior Comment	<u>S</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

Canaral	Commonts
Generai	Comments

Good smooth driving car.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

Inspected by: **Daryll Timms** Date: 03 May 2018

Name:

Fail	N/A
	1
	~
1	
T	
1	
n of tyre	 es)
4	mm
<u>.</u> 4	mm
3	mm
3	mm
Yes	
103	
1	
1	<u> </u>
T	
Т	
+	
1	
+	
1	
1	1
	~
_	

Signature: