

Report ID: 17,876,190 Version: 4 10 May 2018 Created:

Make:	Nissan	Model:	Murano	Body Style:	SUV		Pass	Fail	N/A
Year:	2,005	Registration:	GZQ478	Reg Expiry:	24 Jul 2018	Engine			L
WoF Expiry:		Odometer:	214,891 Kms	Good No:	17876190	Oil level	~		
VIN:	7AT0DH74X13004441	Next Service:	Just Serviced	Service Histor		Smoke & fumes	~		
			Just Scifficed			Performance	~		<u> </u>
	port is not a warranty		с I II	.		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	sc	-0	SC SC			Radiator / Hoses (visual)	~		
S = scratch	STO	A CO			T	Transmission	•		
D = dent	ISC 6			1n-		Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack	ect			+		Clutch			~
P = pin dent	Ho				JUII ——	CV joints	~		
* = decals	sc w QIC			AL-		Wheel bearings	-		
SC = stone chi	ps US	VA		JAL)	& <u> </u>	Brakes	~		
W = significant scuffs SC W W W SC						Performance			<u> </u>
		Note: con	ne defects & blemishes	may not be disr		Hand Brake	~ ~		
Body Insp	pection Comments	Note. son	le délects & blemisnes	s may not be disp	hayed in the diagram		-	-f +	
					Tyres (lowest observed tread depth of tyres)				
						Left front	5.		mm
						Right front	5.		mm
						Left rear	5.		mm
Conditions During Body Inspection: Dry						Right rear	5.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	meenspeede				Suspension			1
						Suspension performance	~		
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			T
Interior Comments						Operation 🖌			
Average						Electrical / Accessories			
Seats	/weitige					Head lights	~		-
Carpets	Good					Tail lights	~		<u> </u>
	Good					Indicators	~		-
Panels						Dashboard warning lights	~		<u> </u>
Dashboa	rd Good					Wipers (front & rear)	~		<u> </u>
	-					Window winder FL	~		
Ganaral	<u>Comments</u>					Window winder FR	~		<u> </u>
						Window winder RL	~		<u> </u>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
L						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Enging Ti	ming Machanism	T '. '				Remote locking	~		<u> </u>
-	ming Mechanism:	Timing (Vras		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspecte	d by: Jeff Luke					Date: 03 May 20)18		

I have read and understood this condition guide.

Name:

Signature: