

Report ID: 17,877,288 Version: 3 09 Nov 2018 Created:

Make:	Toyota	Model:	Corolla	Body Style: Sedan][]	Pass	Fail	N/A
Year:	2010	Registration:		Reg Expiry:	Engine			<u> </u>
WoF Expiry:		Odometer:	183,867 Kms	Good No: 17877288	Oil level	×		
VIN:	JTNBU56EX0J056093	Next Service:	-,	Service History: No	Smoke & fumes	×		+
					Performance	×		+
	port is not a warranty		for one such th		Noise	×		+
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Cooling System			
					Coolant condition			
					Performance	×		
Key:	S SC W	-0	S P		Radiator / Hoses (visual)	×		
S = scratch	Re	A U			Transmission			
D = dent	s sc			EID SD	Operation	×		T
R = rust PT = paint def				T OHH	Noise	×		
C = crack				SC	Clutch	~		×
P = pin dent	Ho				CV joints	×		~
* = decals	ssc 916				Wheel bearings	×		
SC = stone chips					Brakes	3		
W = significan	t scuffs		SP SP	W SP	Performance	×		<u> </u>
		Note: som	e defects & blemish	es may not be displayed in the diagram	Hand Brake	^ X		
Body inspection comments					Tyres (lowest observed tread			
Stone chips front screen. Both headlight lens dirty. Missing front bumper insert for the moulding.					Left front	4.5 mm		
					Right front	4.		mm
					Left rear	3.		mm
Conditions During Body Inspection: Dry					Right rear		3.5 mm	
Conditions During Body Inspection: Dry					Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments					Suspension			
FWD. Engin	e n trans fluid leaks.				Suspension performance	×		
					Steering performance	×		
					Shock absorbers	×		
					Air Conditioning / Heater			<u> </u>
					Operation	×		
Interior Comments					Electrical / Accessories			
Seats	Good				Head lights	x		
	Cood				Tail lights	×		+
Carpets	Good				Indicators	×		+
Panels	Good				Dashboard warning lights	×		+
					Wipers (front & rear)	×		+
Dashboa	ord Good				Window winder FL	×		+
	1				Window winder FR	×		+
General Comments					Window winder RL	×		+
Remote not	t working.				Window winder RR	×		+
					Rear view mirrors	×		+
					Radio (basic test only)	×		+
					CD (basic test only)	×		+
		Number of keys	1					
Road Conditions During Test Drive: Dry					Central locking	×		
					Remote locking			×
Engine Ti	ming Mechanism:	Timing (Chain		Sat. Nav. (basic test only)			×
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:	Reversing camera			×
Inspecte	d by: Eddie Marsters				Date: 04 May 20)18		

I have read and understood this condition guide.

Name:

Signature: