

Report ID: 17,877,392 Version: 1 11 May 2018 Created:

Make:	Mazda	Model:	Mazda6	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,014	Registration:	HNH65	Reg Expiry:	24 May 2018	Engine			
WoF Expiry:	25 Jul 2018	Odometer:	105,728 Kms	Good No:	17877392	Oil level	~		
VIN:	JM0GJ103100134284	Next Service:	109000	Service Histor	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	avation is made	for any and miles as	Dauta hava nat	heen discontined or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
		_				Performance	v		
Key:	s sc	-0	S P SC S P SC	-161-	S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent S D SC S SC S SC						Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent						CV joints	~		•
* = decals SC 99						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S SC S SC S SC						Performance	~		
		Note: som	ne defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread		oftyre))
Tow eye cover missing from rear bumper ,									 mm
						Right front			mm
						Left rear		7	mm
			_			Right rear		5	mm
Conditions During Body Inspection: Dry						Spare	Ū		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
	,					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	v		
Interior Comments						Operation 🖌			
Seats Average						Head lights			
						Tail lights	~		
Carpets	Average					Indicators	~		
	Average					Dashboard warning lights			
Panels						Wipers (front & rear)	~ ~		
Dashboa	ard Average					Window winder FL			
						Window winder FL Window winder FR	~ ~		
General Comments						Window winder FR	<i>v</i> <i>v</i>		
						Window winder RL Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			
						Number of keys	/		
							2		
Road Conditions During Test Drive: Dry						Central locking	v		
Engine Timing Mechanism: Timing Chain						Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		
						Reversing camera	~		
Inspected by: Donovan Matara Date: 11 May 2018									

I have read and understood this condition guide.

Name:

Signature: