

Basic Vehicle Condition Guide

Report ID: 17,878,540

Version:


Created: 14 May 2018

Make: Model: Volkswagen Golf **Body Style:** Hatchback Year: Registration: Reg Expiry: 2,007

WoF Expiry: Odometer: Good No: 02 May 2019 76,197 Kms 17878540 VIN: WVWZZZ1KZ7U00227 **Next Service: Service History:** 86193

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

07 May 2018 Inspected by: **Bobby Zhong** Date:

Name:

Kms:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	v v		
Performance	>		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes		l	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	4	.0	mm
Right front	4.0		mm
Left rear	5.0		mm
Right rear	6.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	V V		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V V V V V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	·		
Remote locking	~		
Sat. Nav. (basic test only)	_		~
Reversing camera			~
3 -			

Signature: