

Make:	Hyundai	Model:	lload	Body Style:	Van	1[Pass	Fail	N/A	
Year:	2,017	Registration:	KKQ3	Reg Expiry:	27 Nov 2018	H	Engine				
WoF Expiry:	28 Feb 2020	Odometer:	18,141 Kms	Good No:	17879201		Oil level	~			
VIN:	KMFWBX7KLHU87124	Next Service:		Service Histor	y: Yes		Smoke & fumes	~			
						il	Performance	~			
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	H	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						H	Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Coolant condition	~			
						1	Performance	~			
Key:		-0	ls	-161-			Radiator / Hoses (visual)	~			
S = scratch							Transmission	-			
D = dent R = rust							Operation	~			
R = rust PT = paint defe				$\left(\left \right\rangle \right)$			Noise	~			
C = crack							Clutch	~			
P = pin dent					세비		CV joints	-		~	
* = decals	616			- No	ELLE		Wheel bearings	~			
SC = stone chips						Brakes				L	
W = significant scuffs S D S D							Performance	~			
		Note: som	ne defects & blemishes	may not be disr	blaved in the diagram		Hand Brake	~			
Body inspection Comments							Tyres (lowest observed tread	•	oftvre	ا مر	
Left hand taillight lens broken. Tail gate wiper arm missing.							Left front 5.5 mm				
							Right front	5.5		mm	
							Left rear	5.5		mm	
Conditions During Pody Inspection:						1	Right rear	1.5		mm	
Conditions During Body Inspection: Dry]	Spare				
Under Carriage & Under Bonnet Inspection Comments]	Spare Yes Yes				
RWD.							Suspension performance	~			
							Steering performance	· ·			
							Shock absorbers	~			
							Air Conditioning / Heater	•			
						1	Operation	~			
Interior Comments							Electrical / Accessories	•			
Seats	Good						Head lights		~		
Jeats							Tail lights	~	•		
Carpets	Good							v v			
Demakr	Good						Dashboard warning lights	~			
Panels							Wipers (front & rear)	v v			
Dashboa	rd Good						Window winder FL	v v			
]	Window winder FR	v v			
General (Comments					1	Window winder RL	~			
Left hand low beam not working.							Window winder RL			レ レ	
							Rear view mirrors	~		~	
							Radio (basic test only)	~			
							CD (basic test only)	~		~	
							Number of keys	1		•	
							Central locking	1			
Road Conditions During Test Drive: Dry]		-			
Engine Ti	ming Mechanism:	Timing (Chain			ון	Remote locking	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:							Sat. Nav. (basic test only)	~		~	
Evidence of Cam Beit Replacement: Not Applicable Kms: Reversing camera											
Inspected by: Eddie Marsters Date: 29 May 2018											

I have read and understood this condition guide.

Name:

Signature: