


<b>Make:</b>	Mitsubishi	<b>Model:</b>	Delica	<b>Body Style:</b>	SUV
<b>Year:</b>	2,002	<b>Registration:</b>	SS8763	<b>Reg Expiry:</b>	17 Feb 2018
<b>WoF Expiry:</b>	14 Jan 2018	<b>Odometer:</b>	350,986 Kms	<b>Good No:</b>	17882429
<b>VIN:</b>	7A8CJ0P0894302279	<b>Next Service:</b>	0	<b>Service History:</b>	No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key:

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



## Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Both front indicators cracked ,stone chip small crack in the windscreen ,both tail lights cracked ,LH side B pillar dented and cracked ,

Conditions During Body Inspection: Dry

## Under Carriage & Under Bonnet Inspection Comments

Minor oil leak ,

## Interior Comments

Seats	ripped and stained and worn,poor condition ,
Carpets	ripped,poor condition ,
Panels	drivers front door trim missing,tail gate trim to,
Dashboard	ignition panel broken ,

## General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
Cooling System			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand Brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front	5	mm	
Right front	6	mm	
Left rear	5	mm	
Right rear	4	mm	
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation		✓	
Electrical / Accessories			
Head lights		✓	
Tail lights	✓		
Indicators		✓	
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking			✓
Remote locking			✓
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Donovan Matara

Date: 07 May 2018

I have read and understood this condition guide.

Name: .....

Signature: .....