

Report ID: 17,883,582 Version: 1 Created: 23 May 2018

Make:	Nissan	Model:	Presage	Body Style:	SUV		Pass	Fail	N/A	
Year:	2,005	Registration:	HMJ803	Reg Expiry:	25 Aug 2018	Engine		-		
WoF Expiry:	02 May 2019	Odometer:	132,071 Kms	Good No:	17883582	Oil level	~			
VIN:	7AT0DH6HX14103973	Next Service:	142000	Service Histor		Smoke & fumes	~			
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		112000		110	Performance	~			
	port is not a warranty		с I I			Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition				
						Performance	~			
Key:	sc	-0	S P SC S P		S SC	Radiator / Hoses (visual)	~			
S = scratch	Se	A CO			X	Transmission	V		I	
D = dent	s sc			The	EID S	Operation	~			
R = rust				10	JHIH	Noise	~			
PT = paint def C = crack	ect III			+		Clutch			~	
P = pin dent	Ho	KI					~		~	
* = decals	sc pp			AL-		CV joints	-			
SC = stone chi	ps US	KA		A		Wheel bearings Brakes	~		<u> </u>	
W = significant scuffs										
		Notorer	ne defects & blemishes		laved in the diagram	Performance Hand Brake	~			
Body Insp	pection Comments	Note: som	ie delects & blemisnes	s may not be disp	layed in the diagram			<i>C</i> .	Ļ	
					Tyres (lowest observed tread depth of tyres)					
						Left front	4		mm	
						Right front	4		mm	
						Left rear	4 mm			
Conditions During Body Inspection: Wet						Right rear	4 mm			
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes			
	inage & onder bor	inet inspectic	on comments			Suspension	,			
						Suspension performance	~		 	
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments Good						Electrical / Accessories				
Seats	Good					Head lights	~			
Carpets	Good					Tail lights	~			
						Indicators	~			
Panels	Good					Dashboard warning lights	~			
Dackher-	Good					Wipers (front & rear)	~			
Dashboa	iiu					Window winder FL	~			
	_					Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry										
	-					Remote locking	~			
-	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspecte	Inspected by: Donovan Matara Date: 23 May 2018									

I have read and understood this condition guide.

Name:

Signature: