

I have read and understood this condition guide.

Report ID: 17,884,170 Version: 2 Created: 24 May 2018

Signature: .....

Make:	BMW	Model:	3 Series	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,007	Registration:	GUA431	Reg Expiry:	01 Jul 2018	Engine			
WoF Expiry:	09 Apr 2019	Odometer:	138,627 Kms	Good No:	17884170	Oil level	~		
VIN:	WBAVA76070NL3464:	Next Service:	147.000	Service Histor		Smoke & fumes	~		
			,			Performance	~		
	port is not a warranty		6	Danta harra nat	harmaltan and an	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
		_				Performance	~		
Key:		-0	S			Radiator / Hoses (visual)	~		
S = scratch						Transmission	•		
D = dent						Operation 🖌			
R = rust PT = paint defect						Noise	~		
C = crack						Clutch	•		~
P = pin dent						CV joints			~
*=decals PT 919						Wheel bearings	~		•
SC = stone chips						Brakes			
W = significant scuffs S S FT S						Performance	~		
		Note: som		may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	ofturo	) )
Stone chip on front windshield						Tyres (lowest observed tread depth of tyres)   Left front 4 mm			
									mm
						Right front		4 mr	
						Left rear	4 mm		
Conditions During Body Inspection: Dry						Right rear 5 mm			mm
Under Carriage & Under Bonnet Inspection Comments						Spare N/A			
						Suspension		-	1
Front wheel free play Engine oil leak						Suspension performance	~		
Marks of coolant leak underneath engine						Steering performance		~	
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
	-					Window winder FL	~		
Conoral	annanta					Window winder FR	~		
General Comments Rubbing noise from front wheels						Window winder RL	~		
i i i i i i i i i i i i i i i i i i i	ise nom nome wheels					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Enging Ti	ning Machanisme	<b></b>	- ·			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Mathew Varghese Date: 24 May 2018									

Name: .....