

Report ID: 17,884,376 Version: 1 Created: 05 Oct 2018

Make:	Holden	Model:	Captiva 7	Body Style:	SUV		Pass	Fail	N/A
Year:	2017	Registration:	кнү952	Reg Expiry:	01 Jun 2018	Engine			
WoF Expiry:	12 Jul 2018	Odometer:	44,566 Kms	Good No:	17884376	Oil level	V		
VIN:	KL3CD2659GB538138	Next Service:	n/a	Service Histor	y: Yes	Smoke & fumes	V		
						Performance		~	
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	V		
						Performance	~		
Key:		-0		-01-	s	Radiator / Hoses (visual)	V		
S = scratch						Transmission			
D = dent	- HE			ZIS	HILS	Operation	~		
R = rust PT = paint def				$\left[\right] \left[\right]$		Noise	~		
C = crack						Clutch			~
P = pin dent					세비	CV joints	~		-
* = decals	- Alt			- Jul	ALC S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S S						Performance	~		
Deskulas	<u></u>	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
								mm	
						Right front		5	mm
						Left rear		5	mm
Conditions During Rody Inspection: West					Right rear	5 mm		-	
Conditions During Body Inspection: Wet						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension Yes			
	-					Suspension performance	~		
						Steering performance	· ·		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Carpets m	issing				Indicators	~		
Panels	Good					Dashboard warning lights	•	~	
raneis						Wipers (front & rear)	~	•	
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
RPM fluctuations						Window winder RR	~		
Engine check light flashing Traction control light stay on						Rear view mirrors	~		
	ntioning it stay on					Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Drv						Central locking	2 V		
Road Con	unions During Test	Dive:	Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
Inspected by: Ca Thach Date: 05 Oct 2018									

I have read and understood this condition guide.

Name:

Signature: