

Report ID: 17,884,557


Version:

18 Aug 2018 Created:

Make:	Holden	Model:	Captiva 7	Body Style:	SUV
Year:	2,017	Registration:	KHY944	Reg Expiry:	01 Jun 2018
WoF Expiry:	27 Jul 2018	Odometer:	44,114 Kms	Good No:	17884557
VIN:	KL3CD2659GB538050	Next Service: Service History: $\gamma_{es}$		/: Yes	

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Crack windscreen

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>					
Seats	Good				
Carpets	Carpets missing				
Panels	Good				
Dashboard	Good				

## **General Comments**

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

Evidence of Cam Belt Replacement: Kms: Not Applicable

18 Aug 2018 Inspected by: Ca Thach Date:

Name: .....

	Pass	Fail	N/A
Engine		•	
Oil level	~		
Smoke & fumes	<b>v</b>		
Performance	~		
Noise	~		
Cooling System	•	•	
Coolant condition	~		
Performance	<b>V</b>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		4	mm
Right front		4	mm
Left rear	3	.5	mm
Right rear	3	.5	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V V V V V V V V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	2		•
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		

Signature: .....