

Report ID: 17,886,211 Version: 1 Created: 05 Jun 2018

Make:	Volkswagen	Model:	Golf	Body Style:	Wagon		Pass	Fail	N/A
Year:	2,014	Registration:	HJJ946	Reg Expiry:	23 Jun 2018	Engine			L
WoF Expiry:	18 Mar 2019	Odometer:	111,336 Kms	Good No:	17886211	Oil level	~		
VIN:	WVWZZZAUZEP56042	Next Service:	121000	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		f	Danta harra nat	haan diamantiad an	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:		-0	S P SC S P SC		S D	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- Alle			1 - L	BIDSW	Operation	~		
R = rust	np			10	JHIH	Noise	~		
PT = paint def C = crack				+	SC	Clutch	V		~
P = pin dent	Ho				JUII —	CV joints	~		
* = decals	s sc pp			SI_	ANR -	,			
SC = stone chips						Wheel bearings	~		
W = significant scuffs S P SC S P SC S P SC S P SC						Brakes			
	5150	Nataraa				Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		<i>с</i> .	
						Tyres (lowest observed tread depth of tyres)			
					Left front	7 mm			
						Right front		7	mm
						Left rear		5	mm
Conditions During Body Inspection: Wet						Right rear	5 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	mage & Under BOI	inet inspectic	on comments			Suspension	1	-	1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
			-•;			Remote locking	~		
Engine Timing Mechanism: Unknown						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
						L	-		
Inspected by: Donovan Matara Date: 05 Jun 2018									
I have read and understood this condition guide. Name:									