

Report ID: 17,888,281 Version: 1 01 Nov 2018 Created:

Make:	Holden	Model:	Cruze	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2017	<b>Registration:</b>	KHU308	<b>Reg Expiry:</b>	01 Jun 2018	Engine	1	1	
WoF Expiry:		Odometer:	43,043 Kms	Good No:	17888281	Oil level	~		
VIN:	6G1PD6EM4GL25060(	Next Service:	unknown	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	P SC	-0	SC P	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			1
D = dent	s sc			ZIS		Operation	~		
R = rust PT = paint def				$\left( \left  \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HID				게	CV joints	~		-
* = decals	sc 916			- Jul	ELL'S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W W W						Performance	~		
Darkelman	<u></u>	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	-	of tyre	es)
Stone chips on screen .									mm
						Right front		, 7	mm
						Left rear		, 4	mm
Conditions During Body Inspection:						Right rear		+ 5	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tidy .	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		<u> </u>
						Operation			
Interior Comments						Electrical / Accessories			
Seats Good						Head lights			
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		+
General Comments						Window winder RL	~		+
Good tidy hatch .						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	I	1
Road Conditions During Test Drive: Drv						Central locking	2 V		
Road Conditions During Test Drive: Dry						Remote locking	~		+
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	+		~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
L									
Inspected by: Daryll Timms Date: 01 Nov 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....