

Report ID: 17,889,105 Version: 3 09 Feb 2019 Created:

Make:	Holden	Model:	Cruze	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2017	Registration:	KHU350	Reg Expiry:	01 Jun 2018	Engine	1	I	1
WoF Expiry:	08 Feb 2020	Odometer:	42,645 Kms	Good No:	17889105	Oil level	~		
VIN:	6G1PD6EM5GL250615	Next Service:	45000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			I
D = dent R = rust	s sc w			715	HILD	Operation	~		
PT = paint def	ect NP	r I		$\left[\left(\right) \right]$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	LICE HE				74116	CV joints	~		
* = decals	SDSC 91			-Jos		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC SC SC						Performance	~		
Podylog	action Commonts	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed trea	l d depth	of tyre	es)
Minor stone chips front screen.								mm	
						Right front		7	mm
						Left rear		3	mm
Conditions During Body Inspection: Dry						Right rear		3	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
<u></u>	Good					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	1					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	I	
Road Conditions During Test Drive: Dry						Central locking	~		
, ,						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
								1	1
Inspected by: Jason Law Date: 09 Feb 2019									

I have read and understood this condition guide.

Name:

Signature: