

Report ID: 17,892,449 Version: 2 Created: 20 Aug 2018

| Make:  | Subaru                 | Model:               | Forester     | Body Style: SUV     |  | Pass        | Fail     | N/A |
|--|------------------------|----------------------|--------------|---------------------|--|-------------|----------|-----|
| Year:  | 2,007                  | Registration:        | . Siester    | Reg Expiry:         | Engine                                       |             |          | L   |
| WoF Expiry:  | 2,007<br>01 May 2019   | Odometer:            | 132,593 Kms  | Good No: 17892449   | Oil level                                    | ~           |          |     |
| VIN:   | 7AT0GF17X18126717      | Next Service:        | 142,582kms   | Service History: No | Smoke & fumes                                | ~           |          |     |
|  |                        |                      | 172,302KIII3 |                     | Performance                                  | ~           |          |     |
|  | port is not a warranty |                      |              |                     | Noise  | ~           |          |     |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends |                        |                      |              |                     | Cooling System                               |             |          |     |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge.  |                        |                      |              |                     | Coolant condition                            |             |          |     |
|  |                        | _                    |              |                     | Performance                                  | ~           |          |     |
| Key:   |                        | -0                   |              |                     | Radiator / Hoses (visual)                    | ~           |          |     |
| S = scratch  |                        |                      |              |                     | Transmission                                 |             |          |     |
|  |                        |                      |              |                     |  | Operation 🖌 |          |     |
| R = rust   |                        |                      |              |                     | Noise  |             |          |     |
| PT = paint defe  | ect 1                  | Clutch               | ~            |                     |  |             |          |     |
| C = crack<br>P = pin dent  |                        |                      |              |                     |  |             |          | ~   |
| * = decals   |                        |                      |              |                     | CV joints                                    | ~           |          |     |
| SC = stone chips   |                        |                      |              |                     | Wheel bearings                               |             |          |     |
| W = significant scuffs   |                        |                      |              |                     |  |             |          |     |
|  |                        | Nation               |              |                     | Performance                                  | ~           |          |     |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram  |                        |                      |              |                     | Hand Brake                                   | ~           | <u> </u> | Ļ   |
|  |                        |                      |              |                     | Tyres (lowest observed tread depth of tyres) |             |          |     |
|  |                        |                      |              |                     | Left front                                   | 5.0 m       |          | mm  |
|  |                        |                      |              |                     | Right front                                  | 5.0 m       |          | mm  |
|  |                        |                      |              |                     | Left rear                                    | 5.0 m       |          | mm  |
| Conditions During Body Inspection: Dry   |                        |                      |              |                     | Right rear                                   | 5.0 mm      |          | mm  |
| Under Comiene & Under Deers of here estimation Comments  |                        |                      |              |                     | Spare  | Yes         |          |     |
| Under Carriage & Under Bonnet Inspection Comments  |                        |                      |              |                     | Suspension                                   |             |          |     |
| OK.  |                        |                      |              |                     | Suspension performance                       | ~           |          |     |
|  |                        |                      |              |                     | Steering performance                         | ~           |          |     |
|  |                        | Shock absorbers      | ~            |                     |  |             |          |     |
|  |                        |                      |              |                     | Air Conditioning / Heater                    |             |          |     |
|  |                        |                      |              |                     | Operation 🖌                                  |             |          |     |
| Interior Comments  |                        |                      |              |                     | Electrical / Accessories                     | ories       |          |     |
| Seats  | Good                   |                      |              |                     | Head lights                                  | ~           |          |     |
| Carpets  | Good                   |                      |              |                     | Tail lights                                  | ~           |          |     |
|  |                        |                      |              |                     | Indicators                                   | ~           |          |     |
| Panels   | Good                   |                      |              |                     | Dashboard warning lights                     | ~           |          |     |
| Dashhaa  | Good                   |                      |              |                     | Wipers (front & rear)                        | ~           |          |     |
| Dashboa  | iiu                    |                      |              |                     | Window winder FL                             | ~           |          |     |
|  | _                      |                      |              |                     | Window winder FR                             | ~           |          |     |
| General Comments   |                        |                      |              |                     | Window winder RL                             | ~           |          |     |
| Tidy AWD v   | vagon .                |                      |              |                     | Window winder RR                             | ~           |          |     |
|  |                        |                      |              |                     | Rear view mirrors                            | ~           |          |     |
|  |                        |                      |              |                     | Radio (basic test only)                      | ~           |          |     |
|  |                        | CD (basic test only) | ~            |                     |  |             |          |     |
|  |                        |                      |              |                     | Number of keys                               | 2           |          |     |
| Road Conditions During Test Drive: Dry Central locking   |                        |                      |              |                     |  |             |          |     |
| Remote locking   |                        |                      |              |                     |  |             |          |     |
| Engine Timing Mechanism: Cambelt Sat. Nav. (basic test only)   |                        |                      |              |                     |  |             |          | ~   |
| Evidence   | of Cam Belt Replac     | Reversing camera     |              |                     | ~  |             |          |     |
|  |                        |                      |              |                     |  |             |          |     |
| Inspected by: Daryll Timms Date: 07 Jun 2018   |                        |                      |              |                     |  |             |          |     |

I have read and understood this condition guide.

Name: .....

Signature: .....