

Report ID: 17,892,483 Version: 1 18 May 2018 Created:

| Make:  | Toyota                   | Model:               | Blade                  | Body Style:        | Hatchback             |   | Pass | Fail | N/A |
|--|--------------------------|----------------------|------------------------|--------------------|-----------------------|---|------|------|-----|
| Year:  | 2,008                    | <b>Registration:</b> |                        | <b>Reg Expiry:</b> |                       | Engine  |      |      |     |
| WoF Expiry:  | 08 May 2019              | Odometer:            | 114,314 Kms            | Good No:           | 17892483              | Oil level   | ~    |      |     |
| VIN:   | 7AT0H656X18002389        | Next Service:        | 124,310kms             | Service Histor     | <b>y:</b> No          | Smoke & fumes                                       | ~    |      |     |
|  |                          |                      |                        |                    |                       | Performance   | ~    |      |     |
|  | port is not a warranty   | eration is made      | for age and mileage    | Parts have not     | been dismantled or    | Noise   | ~    |      |     |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. |                          |                      |                        |                    |                       |   |      |      |     |
| a full mechan  | ical inspection prior to | purchase and th      | his can be arranged fo | or an additional o | charge.               | Coolant condition                                   | ~    |      |     |
|  |                          |                      |                        |                    |                       | Performance   | ~    |      |     |
| Key:   |                          | -0                   |                        |                    |                       | Radiator / Hoses (visual)                           | ~    |      |     |
| S = scratch<br>D = dent  |                          |                      |                        |                    |                       | Transmission  | 1    |      |     |
| B = dent<br>R = rust   |                          |                      |                        | 210                | HIV                   | Operation   | ~    |      |     |
| PT = paint def   | ect NP                   |                      |                        | $\left( \right)$   | 17111                 | Noise   | ~    |      |     |
| C = crack  |                          |                      |                        |                    |                       | Clutch  |      |      | ~   |
| P = pin dent   | HIP                      |                      |                        |                    | 74114                 | CV joints   | ~    |      |     |
| * = decals   | - Alt                    |                      |                        | To .               |                       | Wheel bearings                                      | ~    |      |     |
| SC = stone chips<br>W = significant scuffs   |                          |                      |                        |                    |                       | Brakes  |      |      |     |
| w = significan   |                          |                      |                        |                    |                       | Performance   | ~    |      |     |
| Body Incr  | postion Commonts         | Note: som            | ne defects & blemishes | may not be disp    | played in the diagram | Hand Brake  | ~    |      |     |
| Body Inspection Comments   |                          |                      |                        |                    |                       | <b>Tyres</b> (lowest observed tread depth of tyres) |      |      | es) |
|  |                          |                      |                        |                    |                       | Left front 4 r                                      |      |      | mm  |
|  |                          |                      |                        |                    |                       | Right front   |      | 1    | mm  |
|  |                          |                      |                        |                    |                       | Left rear   |      | 5    | mm  |
| Conditions During Body Inspection: Wet   |                          |                      |                        |                    |                       | Right rear  |      |      | mm  |
|  |                          |                      |                        |                    |                       | Spare Yes   |      |      |     |
| Under Carriage & Under Bonnet Inspection Comments  |                          |                      |                        |                    |                       | Suspension  |      |      |     |
| Tidy .   |                          |                      |                        |                    |                       | Suspension performance                              | ~    |      |     |
|  |                          |                      |                        |                    |                       | Steering performance                                | ~    |      |     |
|  |                          |                      |                        |                    |                       | Shock absorbers                                     | ~    |      |     |
|  |                          |                      |                        |                    |                       | Air Conditioning / Heater                           | I    |      |     |
|  |                          |                      |                        |                    |                       | Operation   | ~    |      |     |
| Interior Comments  |                          |                      |                        |                    |                       | Electrical / Accessories                            |      |      |     |
| Seats  | Good                     |                      |                        |                    |                       | Head lights   | ~    |      |     |
|  | Good                     |                      |                        |                    |                       | Tail lights   | ~    |      |     |
| Carpets  | 0000                     |                      |                        |                    |                       | Indicators  | ~    |      |     |
| Panels   | Good                     |                      |                        |                    |                       | Dashboard warning lights                            | ~    |      |     |
|  | , Good                   |                      |                        |                    |                       | Wipers (front & rear)                               | ~    |      |     |
| Dashboa  | rd                       |                      |                        |                    |                       | Window winder FL                                    | ~    |      |     |
|  | •                        |                      |                        |                    |                       | Window winder FR                                    | ~    |      |     |
| General Comments   |                          |                      |                        |                    | Window winder RL      | ~   |      |      |     |
| Good looking V6 hatch.   |                          |                      |                        |                    |                       | Window winder RR                                    | ~    |      |     |
|  |                          |                      |                        |                    |                       | Rear view mirrors                                   | ~    |      |     |
|  |                          |                      |                        |                    |                       | Radio (basic test only)                             | ~    |      |     |
|  |                          |                      |                        |                    |                       | CD (basic test only)                                | ~    |      |     |
|  |                          |                      |                        |                    |                       | Number of keys                                      | 1    |      |     |
| Road Conditions During Test Drive: Dry   |                          |                      |                        |                    |                       | Central locking                                     | ~    |      |     |
|  |                          |                      |                        |                    |                       | Remote locking                                      | ~    |      |     |
| -  | ming Mechanism:          | Timing (             | Chain                  |                    |                       | Sat. Nav. (basic test only)                         |      |      | ~   |
| Evidence   | of Cam Belt Replac       | ement: N             | lot Applicable         | Kms:               |                       | Reversing camera                                    | ~    |      |     |
|  |                          |                      |                        |                    |                       |   |      |      |     |
| Inspected by: Daryll Timms Date: 18 May 2018   |                          |                      |                        |                    |                       |   |      |      |     |
|  |                          |                      |                        |                    |                       |   |      |      |     |

I have read and understood this condition guide.

Name: .....

Signature: .....