

Report ID: 17,892,844 Version: 2 Created: 25 May 2018

| Make: | Ford | Model: | Falcon | Body Style: | Sedan | | Pass | Fail | N/A |
|--|------------------------|----------------|------------------------|-----------------|----------------------|------------------------------|-----------------------|---------|----------|
| Year: | 2,008 | Registration: | ESW544 | Reg Expiry: | 19 Nov 2018 | Engine | | | L |
| WoF Expiry: | 2,000 21 Nov 2018 | Odometer: | 100,075 Kms | Good No: | 17892844 | Oil level | ~ | | |
| VIN: | 6FPAAAJGSW8Y23312 | Next Service: | 107400 | Service Histor | | Smoke & fumes | ~ | | |
| | 011700000125512 | | 107-100 | | 103 | Performance | ~ | | |
| | port is not a warranty | | | | | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| | | | | | | Coolant condition | | | |
| | | _ | | | | Performance | ~ | | <u> </u> |
| Key: | sc | -0 | | | | Radiator / Hoses (visual) | ~ | | <u> </u> |
| S = scratch | STE | A CO | | | X | Transmission | V | | |
| D = dent | sc dla | | | 1 - L | BID | Operation | ~ | | |
| R = rust | | | | 10 | | Noise | ~ | | <u> </u> |
| PT = paint def C = crack | ect | | | + | SC SC | Clutch | V | | |
| C = Crack P = pin dent | Ho | | | | | | | | ` |
| * = decals | sc pp | | | SI | | CV joints | | | ~ |
| SC = stone chi | ps US | | | 10 | \$P | Wheel bearings | ~ | | |
| W = significan | t scuffs SC | -0 | | | | Brakes | | | |
| | | N | | | | Performance | ~ | | <u> </u> |
| Body Insp | pection Comments | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ✓ | | Ļ |
| | | | | | | Tyres (lowest observed tread | d depth | of tyre | |
| | | | | | | Left front | 5. | 0 | mm |
| | | | | | | Right front | 5. | 0 | mm |
| | | | | | | Left rear | 4. | 0 | mm |
| Conditions During Body Inspection: Wet | | | | | | Right rear | 4.0 mm | | mm |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare | Yes | | |
| Under Ca | rriage & Under Bor | inet Inspectio | on Comments | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation 🖌 | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| Comoto | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | , Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | ra | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | 1 |
| Road Con | ditions During Test | Drive: | Dry | | | Central locking | ~ | | |
| | | | ы | | | Remote locking | ~ | | <u> </u> |
| Engine Ti | ming Mechanism: | Timing (| Chain | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| Inspecte | d by: Brian Hill | | | | | Date: 25 May 20 |)18 | | |

I have read and understood this condition guide.

Name:

Signature: