


<b>Make:</b>	Holden	<b>Model:</b>	Colorado	<b>Body Style:</b>	Utility
<b>Year:</b>	2,013	<b>Registration:</b>	HCW612	<b>Reg Expiry:</b>	29 Jul 2018
<b>WoF Expiry:</b>	06 Nov 2018	<b>Odometer:</b>	186,552 Kms	<b>Good No:</b>	17894198
<b>VIN:</b>	MMU148FK0EH60254	<b>Next Service:</b>	192,000kms	<b>Service History:</b>	Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key:

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



## Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Stone chips in front windscreen. Crack in left side wing mirror cover. Both right & left roof mouldings have broken clips & are not fitting correctly.

Conditions During Body Inspection: Dry

## Under Carriage & Under Bonnet Inspection Comments

Tidy.

## Interior Comments

Seats	hole worn in drivers seat.
Carpets	worn on drivers side.
Panels	gear knob paint worn.
Dashboard	Good

## General Comments

Left side electric wing mirror not working with switch.  
Good 4x4 d/cab ute.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	7.8	mm	
Right front	8.2	mm	
Left rear	3.5	mm	
Right rear	3.3	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors		✓	
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Daryll Timms

Date: 16 Jul 2018

I have read and understood this condition guide.

Name: .....

Signature: .....