

Report ID: 17,895,123 Version: 2 Created: 14 May 2018

Make:	Toyota	Model:	Hiace	Body Style:	Van		Pass	Fail	N/A
Year:	2,014	Registration:		Reg Expiry:		Engine			
WoF Expiry:	11 May 2019	Odometer:	86,103 Kms	Good No:	17895123	Oil level	~		
VIN:	7AT0H60FX18193753	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		$-\infty$				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust				210	HIV	Operation	~		
PT = paint defe	ect NP			$\left(\right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				74114	CV joints			~
*= decals						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significan						Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	5	.0	mm
						Right front	5.	.0	mm
						Left rear	5.	.0	mm
Conditions During Body Inspection: Wet						Right rear	5.	5.0 m	
Vice						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1	1	
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashta	Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	3		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Bobby Zhong Date: 12 May 2018									
Inspected by. Bobby Zilbing Date: 12 Mdy 2018									

I have read and understood this condition guide.

Name: