

Basic Vehicle Condition Guide

Report ID: 17,895,609

Version: 3

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Operation

Noise

Clutch

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Right front

Coolant condition Performance

Radiator / Hoses (visual)

Created: 13 Jul 2018

Pass

1

/

/

V

1

J

N/A

mm

mm

mm

mm

~

6.0

5.0

6.0

1

/

/

1

/

2


Yes

Fail

Make: Model: **Body Style:** Hatchback Ford **Focus** Year: Registration: **Reg Expiry:** 2,004 FLA930 10 Jul 2018 WoF Expiry: **Odometer: Good No:** 03 May 2019 104,740 Kms 17895609 VIN: WF0BXXGCDB3M3439 **Next Service: Service History:** 112000 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Tidy

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Stuart Melbourne

I have read and understood this condition guide.

	Sat. Nav. (basic test only)
Kms:	Reversing camera
	Date: 14 May 2018
Name:	Signature: